

Form Approved
OMB No. 2010-0019
Approval Expires 12-31

CAS# 91-08-7

CONTAINS NO CBI

When completed, send this form to:

Document Processing Center
Office of Toxic Substances, TS-790
U.S. Environmental Protection Agency
401 M Street, SW
Washington, DC 20460
Attention: CAIR Reporting Office

For Agency Use Only:

Date of Receipt:

Document

Control Number:

Docket Number: ____

EPA Form 7710-52

90-900000045 SEPA-OTS

001034049L

		GENERAL REPORTING INFORMATION
1.01	Th	is Comprehensive Assessment Information Rule (CAIR) Reporting Form has been
<u>CBI</u>	cor	mpleted in response to the <u>Federal Register</u> Notice of $[\overline{f}]\overline{2}$ $[\overline{Z}]$ $[\overline{Z}]$ $[\overline{S}]$ $[\overline{S}]$
[]	a.	If a Chemical Abstracts Service Number (CAS No.) is provided in the Federal
		Register, list the CAS No
	ъ.	If a chemical substance CAS No. is not provided in the <u>Federal Register</u> , list either (i) the chemical name, (ii) the mixture name, or (iii) the trade name of the chemical substance as provided in the <u>Federal Register</u> .
		(i) Chemical name as listed in the rule
		(ii) Name of mixture as listed in the rule
		(iii) Trade name as listed in the rule
	c.	If a chemical category is provided in the <u>Federal Register</u> , report the name of the category as listed in the rule, the chemical substance CAS No. you are reporting on which falls under the listed category, and the chemical name of t substance you are reporting on which falls under the listed category.
		Name of category as listed in the rule
		CAS No. of chemical substance [_]_]_]_]_]_]_]_]_[]_]-[_]
		Name of chemical substance
.02	Ide	ntify your reporting status under CAIR by circling the appropriate response(s).
31	Man	ufacturer
_J	Impo	orter
	Prod	cessor
	X/P	manufacturer reporting for customer who is a processor
	X/P	processor reporting for customer who is a processor

CBI	in the above-listed Federal Register Notice?
	Yes Go to question 1.3
\'	No
	a. Do you manufacture, import, or process the listed substance and distribute it under a trade name(s) different than that listed in the Federal Register Notice Circle the appropriate response.
<u>CBI</u>	Yes
	No
	b. Check the appropriate box below:
	[] You have chosen to notify your customers of their reporting obligations
	Provide the trade name(s)
	[] You have chosen to report for your customers
	[] You have submitted the trade name(s) to EPA one day after the effective date of the rule in the Federal Register Notice under which you are reporting.
1.05	If you buy a trade name product and are reporting because you were notified of your reporting requirements by your trade name supplier, provide that trade name.
<u>CBI</u>	Trade name Stepanfoam G-308-T
[_]	Is the trade name product a mixture? Circle the appropriate response.
	ïes
	No
1.06 CBI	Certification The person who is responsible for the completion of this form mus sign the certification statement below:
[_]	"I hereby certify that, to the best of my knowledge and belief, all information entered on this form is complete and accurate."
	David Wilson Washur 8-2-90 NAME SIGNATURE DATE SIGNED
	Mgn Healthy Safety (315) 456 - 2965

1.07 <u>CBI</u>	with the required information on a CAIR Reporting Form for the listed substance				
	"I hereby certify that, to information which I have r to EPA within the past 3 y period specified in the ru	not included i years and is o	In this CAIR Reporting F	form has been submitte	
NA					
مسي	NAME		SIGNATURE	DATE SIGNED	
	TITLE	(TELEPHONE NO.	DATE OF PREVIOUS SUBMISSION	
1.08 <u>CBI</u>	CBI Certification If yo certify that the following those confidentiality class "My company has taken meas and it will continue to taken, reasonably ascertain using legitimate means (or a judicial or quasi-judician information is not publicated to the publication of the public	g statements to ims which you sures to prote ake these meas nable by other than disciply available of the state of the sta	ect the confidentiality sures; the information repersons (other than go covery based on a showing y) without my company's elsewhere; and disclosure	of the information, is not, and has not overnment bodies) by ng of special need in consent; the re of the information	
NA	NAME NAME		SIGNATURE	DATE SIGNED	
	TITLE	(TELEPHONE NO		
(Mark (X) this box if you a	ttach a conti	nuation sheet.		

[] Mark (X) this box if you attach a continuation s	sh ee t .
------------------------------------------------------	------------------

1.11	Parent Company Identification
(<u> </u>	Name []
1.12	Technical Contact
<u>CBI</u>	Name [D]A]Y][]D][]T][W]][]S]O]N][]][][]][][][][][][][][][][][][][][
	[S] Y R A C U S E _ _ _ _ _ _ _ _ _
	$[\frac{N}{N}]\frac{Y}{State}$ $[\frac{1}{3}]\frac{2}{2}]\frac{1}{2}$ $[\frac{4}{8}]\frac{Y}{Y}$
	Telephone Number $[3]\overline{1}5]-[4]\overline{5}\overline{6}-[2]\overline{4}\overline{6}$
1.13	This reporting year is from $[\overline{o}]\overline{I}$ $[\overline{8}]\overline{8}$ to $[\overline{I}]\overline{2}$ $[\overline{8}]$ Ho. $[\overline{I}]$
	Mark (X) this box if you attach a continuation sheet.

1.14	Facility Acquired If you purchased this facility during the reporting year, provide the following information about the seller:
CBI	Name of Seller []]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]
((
	Employer ID Number
	Contact Person []]]]]]]]]]]]]]]]]]
1.15	Facility Sold If you sold this facility during the reporting year, provide the following information about the buyer:
CBI	Name of Buyer []]]]]]]]]]]]]]]]]]
((_ _ _ _ _ _ _ _ _ _ _ _ _ _ City ((_ _ _ _ _ _
	Employer ID Number
	Contact Person []]]]]]]]]]]]]]]]]]
[_]	Mark (X) this box if you attach a continuation sheet.

31	was manufactured, imported, or processed at your facility during the r Classification	uantity (kg)
_]		
	Manufactured	
	Imported	NA
	Processed (include quantity repackaged)	2.869
	Of that quantity manufactured or imported, report that quantity:	
	In storage at the beginning of the reporting year	MA
	For on-site use or processing	
	For direct commercial distribution (including export)	
	In storage at the end of the reporting year	
	Of that quantity processed, report that quantity:	
	In storage at the beginning of the reporting year	<u>(" U.K.")</u>
	Processed as a reactant (chemical producer)	0
	Processed as a formulation component (mixture producer)	o
	Processed as an article component (article producer)	2.869
	Repackaged (including export)	
	In storage at the end of the reporting year	("U.K.")

<u>-</u> j	Component Name	Supplier Name	Average % Composition by Weight (specify precision, e.g., 45% ± 0.5%)
	2,4- Taluene Diisocyanate	Stepan Co	44 %
	2,6-Taluene Diisocyanate	Stepan Co.	<u> </u>
	("U.K.")	Stepan (o.	<u> </u>

[] Mark (X) this box if you attach a continuation :	sheet
------------------------------------------------------	-------

2.04	State the quantity of the listed substance that your facility manufactured. imported or processed during the 3 corporate fiscal years preceding the reporting year in descending order.
CBI	
[_]	Year ending $\{\overline{\underline{I}}\}\overline{\underline{2}}\}$ $\{\underline{\underline{8}}\}\overline{\underline{7}}$
	Quantity manufactured
	Quantity imported
	Quantity processed
	Year ending $[\overline{1}]\overline{2}$ $[\overline{8}]\overline{6}$ Mo. Year
	Quantity manufactured
	Quantity imported
	Quantity processed
	Year ending
	Quantity manufactured
	Quantity imported
	Quantity processed
2.05 CBI	Specify the manner in which you manufactured the listed substance. Circle all appropriate process types.
	Continuous process
	Semicontinuous process
	Batch process
<u></u> j	Mark (X) this box if you attach a continuation sheet.

2.06 <u>CBI</u>	Specify the manner in appropriate process ty	which you processed ypes.	the listed substance.	. Circle all
[_]	Continuous process	NA		
	Semicontinuous process	· · · · · · · · · · · · · · · · · · ·	• • • • • • • • • • • • • • • • • • • •	******
	Batch process		••••••	•••••
2.07 <u>CBI</u>	State your facility's substance. (If you arquestion.)	name-plate capacity fee a batch manufacture	for manufacturing or er or batch processor	processing the lister, do not answer this
[_]	Manufacturing capacity	·	*****	N_A kg/y
	Processing capacity .			
2.08 CBI	If you intend to incre manufactured, imported year, estimate the inc volume.	, or processed at any	' time after vour cur	rent corporato ficas:
		Manufacturing Quantity (kg)	Importing Quantity (kg)	Processing Quantity (kg)
	Amount of increase	NA	NA	NA
	Amount of decrease	NA	<u>N</u> A	("U.K.")
				·
 _	Mark (X) this box if yo			

2.09	listed substanc substance durin	argest volume manufacturing or processing procese, specify the number of days you manufactured of the reporting year. Also specify the average s type was operated. (If only one or two operates	or processed number of h	the liste
CBI		;	Days/Year	Average Hours/Day
	Process Type #1	(The process type involving the largest quantity of the listed substance.)		
		Manufactured	NA	
		Processed	<u>50</u>	< 15
	Process Type #2	(The process type involving the 2nd largest quantity of the listed substance.)		
		Manufactured	NA	
		Processed	NA	-
	Process Type #3	(The process type involving the 3rd largest quantity of the listed substance.)		
		Manufactured	NA_	
		Processed	<u>NÄ</u>	
2.10 CBI	State the maximum substance that schemical.	um daily inventory and average monthly inventory was stored on-site during the reporting year in	y of the lis the form of	ted a bulk
	Maximum daily in	nventory	•	k
	Average monthly	inventory		k
			•	
<u></u> 1	Mark (X) this bo	ox if you attach a continuation sheet.		

etc.).				Source of
CAS No.	Chemical Name	Byproduct, Coproduct or Impurity ¹	Concentration (%) (specify ± % precision)	products, products, Impuritie
91-08-7	2,6-Toluene Diisocyanate	<u> </u>	1-5 %	Raw mat'l
<u> 584-84-9</u>	2,4-Telvene Dissocyanate	I	1-5%	Raw mat
	llowing codes to designate t	oyproduct, copro	oduct, or impurit	y:
Use the formula is a superior of the superior	ict ict	pyproduct, copro	oduct, or impurit	y:
B = Byprodu C = Coprodu	ict ict	pyproduct, copro	oduct, or impurity	y:
B = Byprodu C = Coprodu	ict ict	oyproduct, copro	oduct, or impurit	y:
B = Byprodu C = Coprodu	ict ict	pyproduct, copro	oduct, or impurity	y:
B = Byprodu C = Coprodu	ict ict	pyproduct, copro	oduct, or impurit	y:
B = Byprodu C = Coprodu	ict ict	pyproduct, copro	oduct, or impurit	y:

2.12 <u>CBI</u>	Existing Product Types Lis imported, or processed using the quantity of listed substatotal volume of listed substaquantity of listed substance listed under column b., and the instructions for further	ince you use funce used during used captivel he types of a	or early on-	nce duri ach prod he repor -site as	ng the reuct type ting year a percer	eporting year. List as a percentage of the Also list the
	Ma _ , _ , I	b. of Quantity nufactured. mported, or Processed		% of Qu Used Ca On-	antity	d. Type of End-Users
	J + K 5	1.470	 	۷5	76	H
	<pre>Use the following codes to de A = Solvent B = Synthetic reactant C = Catalyst/Initiator/Accele Sensitizer D = Inhibitor/Stabilizer/Scar Antioxidant E = Analytical reagent F = Chelator/Coagulant/Seques G = Cleanser/Detergent/Degree H = Lubricant/Friction modifiagent I = Surfactant/Emulsifier J = Flame retardant K = Coating/Binder/Adhesive a</pre>	erator/ venger/ strant aser ier/Antiwear	L = N = O = P = Q = T = U = U = U = U = U = U = U = U = U	Moldable Plastic Dye/Pig Photogrand add Electron Fuel and Explosi Fragrand Pollution Metal a Rheology	izer ment/Colo aphic/Rep itives deposition d fuel ad ve chemic ce/Flavor on contro nal fluid lloy and	eals and additives chemicals of chemicals of chemicals and additives additives
	Use the following codes to de I = Industrial CM = Commercial	CS = Cons	ımer			eral Defense

2.13 <u>CBI</u>	Expected Product Types import, or process using corporate fiscal year. import, or process for substance used during used captively on-site types of end-users for explanation and an example of explanation and an example of explanation and example of explanation explanation and example of explanation exp	ng the listed substa For each use, speceach use as a percethe reporting year. as a percentage of each product type.	nce at any time after ify the quantity you ntage of the total voals the quantities the value listed under the valu	expect to manufacture olume of listed substanter column by and the
	a.	b.	·C•	d .
	Product Types ¹	% of Quantity Manufactured, Imported, or Processed	% of Quantity Used Captively On-Site	Type of End-Users
	J+K	51,4%	NA	<u> </u>
	*Use the following code	es to designate prod	uct types:	
	<pre>A = Solvent B = Synthetic reactant C = Catalyst/Initiator Sensitizer D = Inhibitor/Stabiliz Antioxidant</pre>	/Accelerator/	<pre>M = Plasticizer N = Dye/Pigment/Colo 0 = Photographic/Rep and additives</pre>	
	E = Analytical reagent	:	Q = Fuel and fuel ac	on/Plating chemicals ditives
	<pre>F = Chelator/Coagulant G = Cleanser/Detergent</pre>	:/Sequestrant :/Degreaser	<pre>R = Explosive chemic S = Fragrance/Flavor</pre>	
	<pre>H = Lubricant/Friction agent I = Surfactant/Emulsif J = Flame retardant K = Coating/Binder/Adh</pre>	n modifier/Antiwear	T = Pollution control U = Functional fluid V = Metal alloy and W = Rheological modi	ol chemicals is and additives additives ifier
	_			
	² Use the following code I = Industrial CM = Commercial	CS = Cons		<u>deral De</u> fense
	Mark (X) this box if yo	ou attach a continua	tion sheet.	

a.	b.	c. Average % Composition of	d.
Product Type ¹	Final Product's Physical Form	Listed Substance in Final Product	Type of End-Use
N			
¹ Use the following c	odes to designate pro	duct types:	
A = Solvent		L = Moldable/Castable	/Rubber and a
B = Synthetic react		M = Plasticizer	
C = Catalyst/Initia	tor/Accelerator/	N = Dye/Pigment/Color	ant/Ink and a
Sensitizer	• •	<pre>0 = Photographic/Repr</pre>	ographic chem
D = Inhibitor/Stabi	lizer/Scavenger/	and additives	
Antioxidant		P = Electrodeposition	
E = Analytical reag		Q = Fuel and fuel add	
F = Chelator/Coagul		R = Explosive chemica	
G = Cleanser/Deterg		S = Fragrance/Flavor	
	ion modifier/Antivear		
<pre>agent I = Surfactant/Emul.</pre>	aifia-	U = Functional fluids	
J = Flame retardant		V = Metal alloy and a	
		<pre>W = Rheological modif es X = Other (specify)</pre>	161
		e final product's physic	al form:
	F2 = Cry		
B = Liquid	F3 = Gra		
C = Aqueous solution			
D = Paste	G = Ge		
E = Slurry		er (specify)	
F1 = Powder			**************************************
Use the following co	odes to designate the	type of end-users:	
I = Industrial	CS = Cor		
CM = Commercial	H = Oth	er (specify)	

2.15 CBI	Circl liste	e all applicable modes of transportation used to deliver bulk shipments of the substance to off-site customers.	he
[_]	Truck		
		ar	
	Barge	., Vessel	
	Pipel	ine	
	Plane	·	
	Other	(specify)	
2.16 CBI	or pr of en	omer Use Estimate the quantity of the listed substance used by your custom repared by your customers during the reporting year for use under each categoric use listed (i-iv).	hers ory
	i.	Industrial Products	
	1.	Chemical or mixture	kg/7
		Article	
	ii.	Commercial Products	
	11.	Chemical or mixture	kg/∨
		Article	
			**6 / 3
	iii.	Consumer Products	kg/;
		Chemical of mixed to the control of	
		Article	kg/
	iv.	Other	
		Distribution (excluding export)	kg/
		Export	kg/
		Quantity of substance consumed as reactant	. kg/
		Unknown customer uses	kg/
<u></u>	 Mark	(X) this box if you attach a continuation sheet.	

SECTION 3 PROCESSOR RAW MATERIAL IDENTIFICATION

3.01 CBI	Specify the quantity purchased and the average price for each major source of supply listed. Product tra The average price is the market value of the product substance.	idae ara traatad	
	Source of Supply	Quantity (kg)	Average Prid (S/kg)
	The listed substance was manufactured on-site.		
	The listed substance was transferred from a different company site.		
	The listed substance was purchased directly from a manufacturer or importer.		
	The listed substance was purchased from a distributor or repackager.	2.869	("U.K.")
.02 31	The listed substance was purchased from a mixture producer. Circle all applicable modes of transportation used t your facility.	o deliver the li	sted substance
<u> </u>	Circle all applicable modes of transportation used t		

3.03 <u>CBI</u>	a.	Circle all applicable containers used to transport the listed substance to your facility.
[_]		Bags
		Boxes
		Free standing tank cylinders
		Tank rail cars
		Hopper cars
		Tank trucks
		Hopper trucks
		Drums 3
		Pipeline
		Other (specify)10
	ь.	If the listed substance is transported in pressurized tank cylinders, tank rail cars, or tank trucks, state the pressure of the tanks.
		Tank cylinders mmHg
NA)		Tank rail cars mmHg
		Tank trucks mmHg
		•
	Mark	(X) this box if you attach a continuation sheet.

amount of mixture proce Trade Name	Supplier or	Average % Composition by Weight	Amount Processed
Stepanfoam G-308-T	Manufacturer Stepan Co.	(specify ± % precision) 11 %	_(kg/yr)

reporting year in the tor	e listed substance used as a room of a class I chemical, class by weight, of the listed subs	ss II chemical, or polymer, stance.
	Quantity Used (kg/yr)	<pre>% Composition b Weight of Listed S stance in Raw Mater (specify ± % precis</pre>
Class I chemical	26.1	11 70
Class II chemical		
Polymer		

[] Mark (X) this box if you attach a continuation sheet.

General Instructions:	
If you are reporting on a mixture as defined in th 4 that are inappropriate to mixtures by stating "N	e glossary, reply to questions in Section A mixture."
For questions 4.06-4.15, if you possess any hazard notice that addresses the information requested, y facsimile in lieu of answering those questions whi	ou may submit a copy or reasonable

BI	substance as it is manu substance in the final	ity for the three major factured, imported, or product form for manufact at the point you begin	rocessed. Measure the turing activities, at	e purity of the the the you
_1	("NA Mixture")	Manufacture	Import	Process
	Technical grade #1	% purity	% purity	% purit
	Technical grade #2	% purity	% purity	% puri:
	Technical grade #3	% purity	% purity	% puri
	Major = Greatest quant Submit your most recent substance, and for ever	ity of listed substance	manufactured, importe	for the listed
	Major = Greatest quant Submit your most recent substance, and for ever an MSDS that you develor version. Indicate whet appropriate response.	ity of listed substance	manufactured, imported ty Data Sheet (MSDS) the listed substanced by a different sources been submitted by contact the su	for the listed a. If you posse rce, submit your circling the
	Major = Greatest quant Submit your most recent substance, and for ever an MSDS that you develo version. Indicate whet appropriate response. Yes No Indicate whether the MS	ity of listed substance ly updated Material Safe ry formulation containing oped and an MSDS develope ther at least one MSDS ha	manufactured, imported ty Data Sheet (MSDS) the listed substance and by a different source been submitted by company or by a difference of the company of the company or by a difference of the company o	for the listed If you posserce, submit your circling the

HMIS?

HEALTH

REACTIVITY

PERSONAL PROTECTION

:

GENERAL ELECTRIC COMPANY FARRELL ROAD BUILDING ₽ 2 SYRACUSE

NY 13221

NF 00977 01

MATERIAL SAFETY DATA SHEET

DATE: 03/07/90 CUST # 26774-701 P.O.# J85-C2222213790 PAGE:

PRODUCT NAME: STEPANFOAM G-308-T (MOD) PRODUCT NUMBER: 188608

STEPAN COMPANY NORTHFIELD, IL. 60093

MEDICAL: CHEMTREC:

1-800-228-5635

(708) 446-7500

1-800-424-9300

EMERGENCY INFORMATION

******************************** SECTION I: GENERAL INFORMATION \$

PRODUCT NUMBER: 188608 PRODUCT NAME: STEPANFOAM G-308-T (MOD) PRODUCT CLASS: TOLUENE DIISOCYANATE.

PRECAUTIONS: POISON.

REFER TO BILL OF LADING OR CONTAINER LABEL FOR DOT OR OTHER TRANSPORTATION HAZARD CLASSIFICATION, IF ANY.

SECTION II: HAZARDOUS INGREDIENTS ≎

INGREDIENT (CAS #)

ACGIH TLV OSHA PEL (PPM) (PPM)

OTHER

(CONTINUED)

NF 00977 01

MATERIAL SAFETY DATA SHEET

DATE: 03/07/90 CUST # 26774-701 P.O.# J85-C2222213790 PAGE:

PRODUCT NUMBER: 188608 PRODUCT NAME: STEPANFOAM G-308-T (MOD)

TOLUENE-2,4-DIISOCYANATE (TDI) (C) 0.005 0.005 SARA 313

(584-84-9)

448

TOLUENE-2,6-DIISOCYANATE (TDI) (C) 0.005 0.005 SARA 313

(91-08-7)

11%

NE = NOT ESTABLISHED.

NL = NOT LISTED.

(C) = IDENTIFIED AS A CARCINOGEN BY OSHA, IARC, OR NTP.

OVER 200 DEG F. (93 DEG C.).

% VOLATILE BY WEIGHT:

NIL

BOILING POINT:

EVAPORATION RATE: ESTIMATED SLOWER THAN ETHYL ETHER.

VAPOR DENSITY: ESTIMATED HEAVIER THAN AIR. WEIGHT PER GALLON:

10.0 LBS.

FLASH POINT (SETA FLASH CLOSED CUP):

OVER 200 DEG F. (93 DEG C.).

EXPLOSIVE LIMITS:

LOWER:

1%

EXTINGUISHING MEDIA: DRY CHEMICAL, CARBON DIOXIDE, FOAM, OR

WATER FOG. CLASS BC, ABC FIRE EXTINGUISHER.

SPECIAL FIRE FIGHTING PROCEDURES: SELF-CONTAINED POSITIVE PRESSURE BREATHING APPARATUS AND PROTECTIVE

CLOTHING SHOULD BE WORN IN FIGHT-ING FIRES INVOLVING CHEMICALS.

UNUSUAL FIRE AND EXPLOSION HAZARDS: NONE KNOWN.

STABILITY: STABLE HAZARDOUS POLYMERIZATION: WILL NOT OCCUR

(CONTINUED)

NF 00977 01

MATERIAL SAFETY DATA SHEET

DATE: 03/07/90 CUST # 26774-701 P.O.# J85-C2222213790 PAGE: PRODUCT NUMBER: 188608 PRODUCT NAME: STEPANFOAM G-308-T (MOD)

SMALL SPILLS: SOAK UP WITH ABSORBANT, SHOVEL INTO WASTE CONTAINER, FLUSH AREA WITH WATER.

LARGE SPILLS: RECOVER LIQUID FOR REPROCESSING OR DISPOSAL.

WASTE DISPOSAL: RECOVER MATERIAL OR DISPOSE (INCINERATION IS

PREFERRED) IN ACCORDANCE WITH ALL APPLICABLE FEDERAL,

STATE, AND LOCAL REGULATIONS. MATERIAL COLLECTED WITH

ABSORBANT MAY BE DISPOSED IN A PERMITTED LANDFILL IN

ACCORDANCE WITH FEDERAL, STATE, AND LOCAL REGULATIONS.

EMPTY CONTAINER MAY RETAIN VAPOR OR PRODUCT RESIDUE.

OBSERVE ALL LABELED SAFEGUARDS UNTIL CONTAINER IS

CLEANED, RECONDITIONED, OR DESTROYED.

EYE PROTECTION: WEAR FULL FACE SHIELD OR GOGGLES WHEN HANDLING. PROTECTIVE GLOVES: USE IMPERVIOUS GLOVES.

RESPIRATORY PROTECTION:

IF VAPORS ARE PRESENT, USE NIOSH OR MSHA APPROVED RESPIRATOR FO ORGANIC VAPORS, AIR-LINE RESPIRATOR, OR A SELF-CONTAINED BREATHING APPARATUS.

VENTILATION:

USE VENTILATION ADEQUATE TO KEEP HAZARDOUS INGREDIENTS BELOW THEIR TLV (SEE SECTION II).

OTHER PROTECTIVE EQUIPMENT:

WEAR PROTECTIVE CLOTHING TO PREVENT REPEATED OR PROLONGED CONTACT.

EYE WASH STATION AND SAFETY SHOWER SHOULD BE NEAR WORK AREA.

HANDLING AND STORAGE:

AVOID OVERHEATING OR FREEZING.

AVOID OPEN FIRE OR FLAME.

OTHER PRECAUTIONS:

SPILLED MATERIAL IS SLIPPERY. WASH THOROUGHLY AFTER HANDLING. INGESTED, CALL A PHYSICIAN.

DO NOT POUR INTO DRAINS, AS SOLIDS THAT FORM WILL PLUG SEWERS.

1% AMMONIA MAY BE USED TO NEUTRALIZE SPILLS.

NEITHER THIS DATA SHEET NOR ANY STATEMENT CONTAINED HEREIN GRANTS OR EXTENDS ANY LICENSE, EXPRESS OR IMPLIED, IN CONNECTION WITH PATENTS ISSUED OR PENDING WHICH MAY BE THE PROPERTY OF THE MANUFACTURER OR OTHERS. THE INFORMATION IN (CONTINUED)

MATERIAL SAFETY DATA SHEET

NF 00977 01

CUST # 26774-701 P.O.# J85-C2222213790 DATE: 03/07/90 PAGE: PRODUCT NAME: STEPANFOAM G-308-T (MOD) PRODUCT NUMBER: 188608

THIS DATA SHEET HAS BEEN ASSEMBLED BY THE MANUFACTURER BASED ON ITS OWN STUD-IES AND ON THE WORK OF OTHERS. THE MANUFACTURER MAKES NO WARRANTIES, EXPRESS OR IMPLIED, AS TO THE ACCURACY, COMPLETENESS, OR ADEQUACY OF THE INFORMATION CONTAINED HEREIN. THE MANUFACTURER SHALL NOT BE LIABLE (REGARDLESS OF FAULT) TO THE VENDEE, THE VENDEE'S EMPLOYEES, OR ANYONE FOR ANY DIRECT, SPECIAL OR CONSEQUENTIAL DAMAGES ARISING OUT OF OR IN CONNECTION WITH THE ACCURACY, COMPLETENESS, ADEQUACY, OR FURNISHING OF SUCH INFORMATION.

(R) REGISTERED TRADEMARK OR APPLICATION PENDING.

4.03	Submit a copy or reasonable facsimile of any hazard information (other than an MSDS that is provided to your customers/users regarding the listed substance or any
	formulation containing the listed substance. Indicate whether this information has been submitted by circling the appropriate response.
	Yes
	No

For each activity that uses the listed substance, circle all the applicable number of corresponding to each physical state of the listed substance during the activity listed. Physical states for importing and processing activities are determined at the time you import or begin to process the listed substance. Physical states for manufacturing, storage, disposal and transport activities are determined using the final state of the product.

		Phy	sical State		
Activity	Solid Slurr		Liquid	Liquified Gas	Ga
Manufacture	1	2	3	4	۲ •
Import	1	2	3	4	5.
Process		2	3	ů.	r. n
Store	1	2	3	٠,	5
Dispose	1	2	3	•	· ·
Transport	1	2	3	ų	5

[] Mark (X) this box if you attach a continuation sheet.

Physical State	NA)	Manufacture	Import	Process	Store	Dispose	<u>Tr</u>
Dust	<1 micron						
	1 to <5 microns						
	5 to <10 microns						_
Powder	<1 micron						
	1 to <5 microns						
	5 to <10 microns	-		· · · · · · · · · · · · · · · · · · ·			_
Fiber	<1 micron			-			
	1 to <5 microns						
	5 to <10 microns						_
Aerosol	<1 micron	-					
	1 to <5 microns						_
	5 to <10 microns						
						٠	

SECTION 5 ENVIRONMENTAL FATE

5.01	Ind	icate the rate constants for the following transformation processes.	
	a.	Photolysis:	
		Absorption spectrum coefficient (peak) ("U.K.") (1/M cm) at	a.m
		Reaction quantum yield, 6	_ mm
		Direct photolysis rate constant, k_p , at $\binom{n_{v.k.}}{v.k.}$ 1/hr	latiti
	ъ.	Oxidation constants at 25°C:	-
		For 10, (singlet oxygen), k _{ox}	1/8
		For RO ₂ (peroxy radical), k _{ox}	_ 1/8
	c.	Five-day biochemical oxygen demand, BOD, ("V.K.")	mg/
	d.	Biotransformation rate constant:	
		For bacterial transformation in water, $k_b \dots \frac{\binom{n}{U.K.}}{2}$	_ 1/
		Specify culture	
	е.	Hydrolysis rate constants:	
		For base-promoted process, k_{B}	1/
		For acid-promoted process, k,	1/
		For neutral process, k _N	1/
	f.	Chemical reduction rate (specify conditions) ("U.K.")	
		•	
	g.	Other (such as spontaneous degradation) $(U, K,)$	
AII	e۸	vironmental Fate data is unknown according to	
		Co. and Olin Chem. Mfg.	
`	·		

5.02	2 a.	Specify the half-life of th	ne listed substa	ance in the following m	media.
		Media		Half-life (specify u	ınits)
		Groundwater	("U.K.")		
		Atmosphere			
		Surface water	<u> </u>		
		Soil			
	b.	Identify the listed substan life greater than 24 hours.	ce's known tran	sformation products th	at have a half-
		CAS No.	Name	Half-life (specify units)	Media
		("v.K.")		in	
				in	
				in	
				in	
5.03		eify the octanol-water particle of calculation or determined			at 25
.04		ify the soil-water partition type			at 25
.05	Spec coef	ify the organic carbon-water ficient, K	partition	<u>("u.k.")</u>	at 25
.06	Spec	ify the Henry's Law Constant	:, н	<u>(</u> "u.K.")	atm-m³/mo

Bioconcentration Factor (*U.K.*)		Species		Test	.
<u> </u>			····		
	<u> </u>				
¹ Use the following codes to	designate	the type of	test:		
F = Flowthrough					
S = Static					
			•		

6.04 CBI	For each market listed below, state t the listed substance sold or transfer	he quantity sold and the red in bulk during the r	e total sales value of seporting year.
17		Quantity Sold or	Total Sales
	Market	Transferred (kg/yr)	Value (S.yr)
	Retail sales		
	Distribution Wholesalers		
	Distribution Retailers		
	Intra-company transfer		
	Repackagers	/	
	Mixture producers		
	Article producers		
	Other chemical manufacturers or processors		
	Exporters		
	Other (specify)		_
/			
6.05	Substitutes List all known commerc	ially feasible substitu	tes that you know exis:
CBI	for the listed substance and state th feasible substitute is one which is e in your current operation, and which performance in its end uses.	conomically and technological	ogically feasible to us
	Substitute		Cost (S/kg)
	None Available		<u> </u>
	THORE MORNABIE		
			•
[_]	Mark (X) this box if you attach a con	tinuation sheet.	

General Instructions:

For questions 7.04-7.06, provide a separate response for each process block flow diagra provided in questions 7.01, 7.02, and 7.03. Identify the process type from which the information is extracted.

PART A MANUFACTURING AND PROCESSING PROCESS TYPE DESCRIPTION

7.01 In accordance with the instructions, provide a process block flow diagram showing major (greatest volume) process type involving the listed substance.

CBI Encapsulating 78) PART A (I at [7A] PART B (Resin) 7.2) WEIGH CONTAINER WEIGH CONTAINER/MIXER Polymer Encopsulating ENTCONTAINER SPENT TRRER CONTAINER MOLD (Polymer Encapsulating (7F)\ -(7G) VENT (Polymer Encapsulating) 7,4) Oven FINAL PRODUCT ELECTRONIC MODULE

[] Mark (X) this be f you attach a continuation sheet.

7.03 In accordance with the instructions, provide a process block flow diagram showing a process emission streams and emission points that contain the listed substance and which, if combined, would total at least 90 percent of all facility emissions if not treated before emission into the environment. If all such emissions are released from one process type, provide a process block flow diagram using the instructions for question 7.01. If all such emissions are released from more than one process type, provide a process block flow diagram showing each process type as a separate block.				
CBI	Process type ENCAPSULATING			
(78,	7.2) - (7() SPENT CONTAINER (TDI Residuals)			
(7A,71	3,7.1,7.2,7.3) - (TF) WORK AREA VENTILL ATION			
(7.4)	(7G) Oven VENTILLATION			
<u> </u>	Mark (X) this box if you attach a continuation sheet.			

Process type ENCAPSULATING							
Unit Operation ID Number	Typical Equipment Type	Operating Temperature Range (°C)	Operating Pressure Range (mm Hg)	Vessel Composition			
7.1	Cup	AMBIENT	ATMOSPHERIC	Paper			
7.2	Cup	AMBIENT	ATMOSPHERIC	Paper			
7.3 (a) 50% 50% 50% 500 T.4	Mold	AMBIENT 11 60°C	ATIMOSPHERIC N ATMOSPHERIC	aluminum rubber steel			
				• • .			

7.05	process block	process stream identified in your pr flow diagram is provided for more th complete it separately for each proce	an one process type	agram(s). If a , photocopy thi
CBI	Process type	Encapsulating		
	Process Stream ID Code	Process Stream Description	Physical State	Stream Flow (kg/yr)
	7A	Raw Mat1 - Resin	OL	14.78
	7B	Raw Mat'1 - G-308-T	OL	26.1
	<u>7C</u>	Residual in Cup - G-308-T	OL	.075
	70	Spent container and stirrer-mix	_50	_NA
	<u>TE</u>	Circuit Board	50	NA .
	<u>JF</u>	Worker Area VENTILLATION	<u>GU</u>	("U.K.")
	7G_	OVER VENTILLATION	<u> </u>	("U.K.")
	<u>7H</u>	ELECTRONIC MODULE	_\$0	NA
	GC = Gas (cc GU = Gas (ur SO = Solid SY = Sludge AL = Aqueous OL = Organic	s liquid	pressure) nd pressure)	
<u></u>	1 Mark (Y) thi	s box if you attach a continuation s	heet.	•••

	a.	b.	c.	d.	e.
S	ocess tream Code	Known Compounds ¹	Concentrations ^{2,3} (Z or ppm)	Other Expected Compounds	Estimated Concentratio (% or ppm)
7	A	(Resin) ("U.K.")			
	7B	(Catalyst) 2,6-TDI	1190	<u>CO</u> 2	("U.K")
_	 .	2,4-TDI	44%		
	7 C	(hesid. Catalyst) 2,6-TD1	11 %		
		2,4-TDI	14 %		
	<u>70</u>	NA (Polymer Encapsulat	\		
	7 <u>E</u> 7F	NA (Polymer Encapsulate	d)		
	1 -	(Vapor) Cyanites		<u>Co,</u>	("U.K.")
		ammonia			
-	76	(Vapor) cyanates	\rightarrow		
		ammonia		CO_2	("U.K."
		916			
06 co	ntinued b	elow			
		(NA) Final Product			
_	7 H	(MH) THE THE			
					• • •

7.	.06	(continued)
----	-----	-------------

For each additive package introduced into a process stream, specify the compounds
that are present in each additive package, and the concentration of each component
Assign an additive package number to each additive package and list this number is
column b. (Refer to the instructions for further explanation and an example.
Refer to the glossary for the definition of additive package.)

	ddit age	ive Number				ents of e Packag	ge			Concentrations (% or ppm)
	11		_							
	2	NI								
	3									
<u></u>	4	<u> </u>						· ·		
	5							- - -		
²Use	the	following	codes	to	designate	how the	cond	- centration		determined:
A = E =	Anal Engi	ytical reneering j	sult udgemer	nt/o	calculation	n				
³ Use	the	following	codes	to	designate	how the	сопо	centration	was	measured:
	Volu Weig									

3.01 In accordance with the instruction which describes the treatment process Process type	ess used for residuals i	reatment block flow diagra identified in question 7.0
(7C Spent Cup (Residual)		Transpor to TSD facility
		· ·.

PART	B RESID	DUAL GENERATI	ON AND CHARA	ACTERIZATION								
8.05 CBI	diagram process	n(s). II a r s type, photo	esidual trea copy this qu	itment block fluestion and con	low diagram is mplete it sepa	al treatment be provided for rately for eac and an example	more than or					
[_]	Process type Encapsulating											
	a.	b.	c.	d.	, e.	f.	g.					
	Stream ID Code	Type of Hazardous Waste	Physical State of Residual ²	Known Compounds ³	Concentra- tions (% or ppm) 4,5,6	Other Expected Compounds	Estimated Concentrations (% or ppm)					
	<u>7c</u>	HRET	OL	2 4-TOI	44 %	("U.K.")	(UK")					
		, ,		2,6-TD1	1170	("U.K.")	("UK")					
							·					
				-								
				<u></u>								
				-	-							
							-					
							-					

8.05 continued below

Hark	(X)	this	рох	if	you	attach	a	continuation	sheet

8.05 (continued) 1 Use the following codes to designate the type of hazardous waste: I = Ignitable C = Corrosive R = Reactive E = EP toxicT = ToxicH = Acutely hazardous ²Use the following codes to designate the physical state of the residual: GC = Gas (condensible at ambient temperature and pressure) GU = Gas (uncondensible at ambient temperature and pressure) SO = SolidSY = Sludge or slurry AL = Aqueous liquid OL = Organic liquid IL = Immiscible liquid (specify phases, e.g., 90% water, 10% toluene)

8.05 continued below

a. 03	- (· ~	on	t	i	n	110	ri	١
a v.	- I		OH	L	1	11	ue	•	•

For each additive package introduced into a process stream, specify the compounds
that are present in each additive package, and the concentration of each component
Assign an additive package number to each additive package and list this number in
column d. (Refer to the instructions for further explanation and an example.
Refer to the glossary for the definition of additive package.)

Additive Package Number	Components of Additive Package	Concentrations (% or ppm)
1		
(A) 1 G		
2 (NA	,	
3		-
4		
5		•
⁴ Use the following codes	s to designate how the concentrati	on was determined:
A = Analytical result E = Engineering judgeme	ent/calculation	
8.05 continued below		
[_] Mark (X) this box if you	u attach a continuation sheet.	

8	. ()5	(C	חכ	t	i	n	u	e	d)	
---	-----	----	---	---	----	---	---	---	---	---	---	---	--

5 Use	the	following	codes	to	designate	how	the	concentration	vas	measured:
-------	-----	-----------	-------	----	-----------	-----	-----	---------------	-----	-----------

V = Volume

W = Weight

⁶Specify the analytical test methods used and their detection limits in the table below. Assign a code to each test method used and list those codes in column e.

<u>Code</u>	(NA)	Method	Detection Lim (± ug/l)
1			
2			
3			
4			
_5			
6			

[]	Mark (X) this	box if ye	ou attach	a continuation	sheet.	•
-----	---------	--------	-----------	-----------	----------------	--------	---

a. Stream ID	· b.	c.	d.			
			~ ·	е.	f. Costs for	
	Waste Descripțion		t Residual Quantities	Managemen of Residual	t Off-Site	Char Mana
Code	Code ¹	Code ²	(kg/yr)	On-Site Off-	Site (per kg)	Met
<u>7C</u>	<u>867/869</u>	<u>1sT</u>	.075	100%	<u>(*u.K.*)</u>	<u>55</u>
		Note 3	Residuals	are lab o	aked with o	 ther
		hazardas			transporter a	
			,	TSD facilit	•	
			·			
		-				
			·			
1	codes prov	ided in Exh	ibit 8-1 to	designate the v	aste description	
use the				acordinate time a	asce description	3

	Combustion Location of Chamber Temperature Temperature (°C) Monitor		erature	Residence Time In Combustion Chamber (seconds)		
Incinerator	Primary	Secondary	Primary	Secondary	Primary	Seconda
2						
3						
Indicate by circl Yes	if Office of the appropriate t	of Solid Wast ropriate resp	e survey ha	s been submit	ted in lieu	of respons
No	• • • • • • • • • • • • • • • • • • • •		••••••		•••••	••••••
are used on-Si	te to burn t	ine residuais	hree larges identified	t (by capacit in your proc	y) incinerat ess block or	ors that residual
Incinerator 1	NA	Air Po Control	llution Device ¹		Emission	s Data
3	_					
Indicate by circli	if Office o	of Solid Wast copriate resp	e survey ha onse.	s been submit	ted in lieu	of respon
Yes		••••••	•••••	• • • • • • • • • • • • • • • • • • • •	• • • • • • • • • • •	
¹ Use the follow	ing codes t	o designate		lution contro		
	Indicate by circle res No Complete the form are used on-six treatment block Incinerator 1 2 3 Indicate by circling res No	Incinerator Primary Indicate if Office of by circling the approximate to burn treatment block flow diagrams Indicate if Office of by circling the approximate to burn treatment block flow diagrams Indicate if Office of by circling the approximate to burn treatment block flow diagrams Indicate if Office of by circling the approximate to burn treatment block flow diagrams Indicate if Office of by circling the approximate to burn treatment block flow diagrams Indicate if Office of by circling the approximate to burn treatment block flow diagrams Indicate if Office of by circling the approximate to burn treatment block flow diagrams.	Incinerator Primary Secondary 2 3 Indicate if Office of Solid Wast by circling the appropriate responses No Complete the following table for the tare used on-site to burn the residuals treatment block flow diagram(s). Incinerator 1 2 3 Indicate if Office of Solid Wast by circling the appropriate responses Yes No No No No Ontrol	Temperature (°C) Incinerator Primary Secondary Primary 1 2 3 Indicate if Office of Solid Waste survey has by circling the appropriate response. No Complete the following table for the three larges are used on-site to burn the residuals identified treatment block flow diagram(s). Incinerator 1 2 3 Indicate if Office of Solid Waste survey has by circling the appropriate response. Yes No No No No No No No No No N	Temperature (°C) Monitor Incinerator Primary Secondary Primary Secondary 2 3 Indicate if Office of Solid Waste survey has been submit by circling the appropriate response. No Complete the following table for the three largest (by capacity are used on-site to burn the residuals identified in your process treatment block flow diagram(s). Air Pollution Control Device 1 2 3 Indicate if Office of Solid Waste survey has been submit by circling the appropriate response. Yes No No No No No No No No No N	Chamber Temperature (°C) Monitor Chamber Incinerator Primary Secondary Primary Secondary Primary 2 3 Indicate if Office of Solid Waste survey has been submitted in lieu by circling the appropriate response. No Complete the following table for the three largest (by capacity) incinerate are used on-site to burn the residuals identified in your process block or treatment block flow diagram(s). Air Pollution Emission Avail Incinerator Control Device Avail Air Pollution Emission Avail Indicate if Office of Solid Waste survey has been submitted in lieu

[_]	Data Element	ata are Ma: Hourly Vorkers	intained for: Salaried Vorkers	Year in Which Data Collection Began	Number of Years Record Are Maintain
	Date of hire	<u> </u>	x	1946	10
	Age at hire		X	1946	10
	Work history of individual				
	before employment at your facility	X_	X	1946	
	Sex	X	<u> </u>	1946	
	Race	X	<u> x</u>	1946	10
	Job titles	X	X	1946	
	Start date for each job title	X_	X	1972	
	End date for each job title	X	X	1972	10
	Work area industrial hygiene monitoring data	X_	X	1968	Permanen
	Personal employee monitoring data	X	X	1968	Permaner
	Employee medical history	X_	X	1946	<u>l'ermaner</u>
	Employee smoking history	X_	X	1979	Permanes
	Accident history		X	1946	Permane
	Retirement date	X	X	1946	10
	Termination date	X	X	1946	10
	Vital status of retirees	X	<u> </u>	1970	Permanen
	Cause of death data		×	1970	Permane

a.	b.	c.	d.	e.
Activity	Process Category	Yearly Quantity (kg)	Total Workers	Tota Worker-H
Manufacture of the	Enclosed	N A	And the second of the second	
listed substance	Controlled Release	N.A		
	Open	NA		
On-site use as	Enclosed	_NA		-
reactant	Controlled Release	_NA		-
	0pen	NA_		
On-site use as nonreactant	Enclosed	_NA	-	
	Controlled Release	NA		
	0pen	NA		***
On-site preparation	Enclosed	NA	-	
of products	Controlled Release	2.869	5	750
	0pen	NA		
			•	,
		,		

9.03	Provide a descriptive jencompasses workers who listed substance.	ob title for each labor category at your facility that may potentially come in contact with or be exposed to the
CBI		
[_]		
	Labor Category	Descriptive Job Title
	A	Potting Operator
	В	,
	С	
	D	
	E	
	F	
	G	
	Н	
	I	
	J	
_1	Mark (X) this box if yo	u attach a continuation sheet.

9.04 In accordance with the instruct indicate associated work areas.	ions, provi	de your prod	cess block flow	diagram(:) and
	= ncapsula			A .	
Potting Op	verator En	compases E	entire Process	. Areq	
(7A) PART B (Resin)	·	(7B) PAR	TA (TOI)		
•			-		
(7.1) WEIGH CONTAINER/MIXER		(7.2) WE	EIGH CONTAINER		
ITAINER			\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	ENT	
(70)	· (7F) \$	IRCUIT IOARD	(7C) co	NTAINER	(-)
(7.3) MOLD (Pelymer Encapsulating)	(1-16	DAKU			(7F)'
(7.4) Oven: (Polymer Encapsulating)	→(7G)V	ENT			
(7H) FINAL PRODUCT	T MODULE				
I''Y ELECTRONIC	1 100 000				· · .
	,				
[_] Mark (X) this box if you atta	ach a contin	nuation shee	et.	_	
	9				

9.05 CBI	may potentially come additional areas not	work area(s) shown in question 9.04 that encompass workers who in contact with or be exposed to the listed substance. Add an shown in the process block flow diagram in question 7.01 or question and complete it separately for each process type.					
[_]	Process type	Encapsulating					
	Work Area ID	Description of Work Areas and Worker Activities					
	1	Hooded work beach (mixing and mold pour)					
	2						
	3						
	4						
	5						
	6						
	7						
	8						
	9						
	10						

9.06 CBI	come in cont	act with or be	ble for each work a ur facility that er e exposed to the li y for each process	icompasses worke isted substance.	rs who may pot	
[_]	Process type					
	Work area	••••••	• • • • • • • • • • • • • • • • • • • •			
	Labor Category	Number of Workers Exposed	Mode of Exposure (e.g., direct skin contact)	Physical State of Listed Substance ¹	Average Length of Exposure Per Day	Number of Days per Year Exposed
	A	5	Direct Skin Conto + Inhalation	OL		50
					-	
						·
- -						
	GC = Gas (contemper GU = Gas (temper include SO = Solid A = 15 minut B = Greater exceedin C = Greater	condensible at tature and pre incondensible tature and pre des fumes, vap	ssure) A at ambient 0 ssure; I ors, etc.) o designate averag es, but not E	Y = Sludge or sl L = Aqueous liqu L = Organic liqu L = Immiscible 1 (specify pha 90% water, 1	lurry uid liquid liquid lses, e.g., l0% toluene) osure per day: 2 hours, but nours 4 hours, but	not
1 !	Mark (X) this	box if you a	ttach a continuati	on sheet.	****	

Photocopy this ques area.	tion and complete it separately for	nute peak exposure levels. or each process type and work
Process type	. Encapsulating	
Work area		
Labor Category	8-hour TWA Exposure Level (ppm, mg/m³, other-specify)	15-Minute Peak Exposure Legentary (ppm, mg/m, other-specif
A	("v.k.")	("U.K.")
		-
	Process type Work area Labor Category	Process type Encapsulating Work area

If	you monitor worke	r exposur	e to the li	sted substa	nce, compl	lete the fo	llowing table
			•				
<u>Sa</u>	mple/Test	Work Area ID	Testing Frequency (per year)	Number of Samples (per test)	Who Samples ¹	Analyzed In-House (Y/N)	Number of Years Record Maintained
	rsonal breathing zone		O		NA	NA	Permanent
	neral work area (air)			-		 	
Wi	pe samples						
Adl	nesive patches	-19-					
Blo	ood samples						
Uri	ine samples	-					
Res	spiratory samples						
A11	lergy tests						-
0th	mer (specify)						
0 t h	mer (specify)						
Oth	er (specify)						-
A B C	e the following co = Plant industrial = Insurance carrie = OSHA consultant	hygienis		takes the	monitorin	ng samples:	
A B C	= Plant industrial = Insurance carrie	hygienis		takes the	monitorin	ng samples	•

_]	Sample Type	(b.1.A)	Sampling and Analyt	ical Methodolo	<u>gy</u>

. 10	If you conduct person specify the following	nal and/or ambies g information fo	nt air monitoring for r each equipment type	r the listed s e used.	ubstance,
l	Equipment Type 1	Detection Limi	t ² Manufacturer	Averaging Time (hr)	Model Numbe
		NA NA			
	Use the following contact A = Passive dosimeter B = Detector tube C = Charcoal filtration	er tion tube with pu		oring equipmen	it types:
	D = Other (specify) Use the following co		e ambient air monito	ring equipment	t types:
	E = Stationary monit F = Stationary monit G = Stationary monit	tors located with tors located with tors located at p ng equipment (spe	nin work area hin facility		
	² Use the following co			its:	
	<pre>A = ppm B = Fibers/cubic cer C = Micrograms/cubic</pre>	ntimeter (f/cc) c meter (µ/m³)			. •
	•				

To	at Domerintis	- n	(mok).	Frequency	y
16	st Description	<u>on</u>	(weekly,	monthly, y	early, etc
	(MA) :	 		
				•	
		,			

PART C ENGINEERING CONTR	ARI	C	ENGINEERING	CONTROLS
--------------------------	-----	---	-------------	----------

Describe the engineering to the listed substance. process type and work are:		ou use to reduce o question and comp	r eliminate wor lete it separa	rker exposur tely for ear
Process type	Encap	sulating		
Engineering Controls	Used (Y/N)	Year Installed	Upgraded	ïear. Upgrades
Ventilation: Local exhaust General dilution	Y	1975	- 	1988
Other (specify)				
Vessel emission controls	_N		N	
Mechanical loading or packaging equipment	14		N	
Other (specify)				

	Mark	(X)	this	pox	if	you	attach	a	continuation	sheet.
--	------	-----	------	-----	----	-----	--------	---	--------------	--------

	the listed substance. the percentage reducti	or process modifications you have year that have resulted in a red For each equipment or process moon in exposure that resulted. Pheore each process type and work a	dification described, s
			rea.
	Process type	11.0000011111	
ţ	Jork area	• • • • • • • • • • • • • • • • • • • •	
-	Equipment o	r Process Modification	Reduction in Wor Exposure Per Year
_			
		(MA)	
_			
_			
			•
			• •
		•	

and work area.

CBI		÷	
[_]	Process type	Encapsulating	
	Work area	· · · · · · · · · · · · · · · · · · ·	
			Wear or
	Eg	uipment Types	Use (Y/N)
	Re	espirators	N
	Sa	fety goggles/glasses	<u> </u>
	Fa	ce shields	N
	Co	veralls	N
	Ві	b aprons	_ N
	Ch	emical-resistant gloves	
	Ot	her (specify)	
	\mathcal{D}	ispesable shop coat	

Describe the personal protective and safety equipment that your workers wear or use in each work area in order to reduce or eliminate their exposure to the listed

substance. Photocopy this question and complete it separately for each process type

9.15	respirato tested, a	s use respirators ype, the work are results avers and find the type and find the type and for	as where th age usage, requency of	e respirat whether or the fit t	ors are us	ed, the type	of
CBI							
[_]	Process t	pe	-				
	Work Area	Respirator Type	r	Average Usage	Fit Tested (Y/N)	Type of Fit Test ²	Frequency of Fit Tests (per year)
		(N	A				
					· · · · · · · · · · · · · · · · · · ·		
	A = Daily B = Veekl C = Month D = Once E = Other	y ly a year (specify) ollowing codes to			,	t:	
	Mark (X) ti	nis box if you at	tach a con	tinuation	sh ee t.		

PART	E WORK PRACTICES							
9.19 <u>CBI</u>	Describe all of the work practices and administrative controls used to reduce or eliminate worker exposure to the listed substance (e.g., restrict entrance only to authorized workers, mark areas with warning signs, insure worker detection and monitoring practices, provide worker training programs, etc.). Photocopy this question and complete it separately for each process type and work area.							
[_]	Process type	Encapsulati	09					
	Work area	•	•					
	1. Employee T	raining.						
	2. Local Exhaus		Work Area					
	-							
9.20	Indicate (X) how often you perform each housekeeping task used to clean up routine leaks or spills of the listed substance. Photocopy this question and complete it separately for each process type and work area.							
	Process type	•	<u>ating</u>					
	Work area	Work area						
	Housekeeping Tasks	Less Than Once Per Day	1-2 Times Per Day	3-4 Times Per Day	More Than 4 Times Per Day			
	Sweeping							
	Vacuuming							
	Water flushing of floors							
	Other (specify)							
	minor wipe-ups	X						

9.21	exposure to the listed substance?	n plan for responding to routine or eme	rgency
	Routine exposure		•
	ïes		• • • • • • • • • •
	No		
	Emergency exposure		
	ïes		
	No		
	If yes, where are copies of the plan	n maintained?	
	Routine exposure:		
	Emergency exposure:		
9.22	Do you have a written leak and spill substance? Circle the appropriate r	l cleanup plan that addresses the liste response.	èd
(Yes MSPS	•••••	C
	No		
	If yes, where are copies of the plan	n maintained? Supervisors Office /Health	+Safety Dep
	Has this plan been coordinated with Circle the appropriate response.	state or local government response org	ganization
	Yes		
	(No)		
9.23	Who is responsible for monitoring we appropriate response.	orker safety at your facility? Circle	the
	Plant safety specialist		
	Insurance carrier		
	OSHA consultant		*******
	Other (specify)		
	Mark (X) this box if you attach a c	continuation sheet.	

General Instructions:

Complete Part E (questions 10.23-10.35) for each non-routine release involving the listed substance that occurred during the reporting year. Report on all releases that are equal to or greater than the listed substance's reportable quantity value, RQ, unless the relea. is federally permitted as defined in 42 U.S.C. 9601, or is specifically excluded under the definition of release as defined in 40 CFR 302.3(22). Reportable quantities are codified in 40 CFR Part 302. If the listed substance is not a hazardous substance under the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 (CERCLA) and thus, does not have an RQ, then report releases that exceed 2,270 kg. If such a substance however, is designated as a CERCLA hazardous substance, then report those releases that at equal to or greater than the RQ. The facility may have answered these questions or simila questions under the Agency's Accidental Release Information Program and may already have this information readily available. Assign a number to each release and use this number throughout this part to identify the release. Releases over more than a 24-hour period at not single releases, i.e., the release of a chemical substance equal to or greater than at RQ must be reported as a separate release for each 24-hour period the release exceeds the RO.

For questions 10.25-10.35, answer the questions for each release identified in question 10.23. Photocopy these questions and complete them separately for each release.

PART A	GENERAL INFORMATION
10.01	Where is your facility located? Circle all appropriate responses.
CBI	
[_]	Industrial area
	Urban area
	Residential area
	Agricultural area
	Rural area
	Adjacent to a park or a recreational area
	Within 1 mile of a navigable waterway
	Within 1 mile of a school, university, hospital, or nursing home facility(
	Within 1 mile of a non-navigable waterway
	Other (specify)
	Mark (X) this box if you attach a continuation sheet.

10.02	Specify the exact location of your is located) in terms of latitude a (UTM) coordinates.	tral poi versal T	nt where particular in the second contract of	process unit Mercader					
	Latitude		43	°7	<u>N 8 '</u> _				
	Longitude		76	_°_15	46 W				
	UTM coordinates Zone	, North	ing	, Eas	ting				
10-03	If you monitor meteorological conditions in the vicinity of your facility, provide the following information.								
	Average annual precipitation inches/yea								
	Predominant wind direction								
10.04	Indicate the depth to groundwater	below your facility							
	Depth to groundwater	•			meters				
10.05 CBI	For each on-site activity listed, listed substance to the environmer Y. N. and NA.)	indicate (Y/N/NA) a nt. (Refer to the in	ll routi nstructi	ne releas ons for a	es of the definition o				
[_]	On-Site Activity	Env <u>Air</u>	vironmental Release Water Land						
	Manufacturing	NA		<u></u>					
	Importing	NA		-					
	Processing	<u> </u>	N		_ 'N				
	Otherwise used	NA							
	Product or residual storage	N		_N					
	Disposal	NA	·						
	Transport	NA							
	Mark (X) this box if you attach a c	continuation short			-				
·—'	(n) this ook it you attach a t	.vcinuation Sheet.							

10.08 CBI	for each process stream process block or resident	technologies used to minimize release am containing the listed substance as dual treatment block flow diagram(s). ately for each process type.	identified in your
[_]	Process type	Encapsulating	
	Stream ID Code	Control Technology	Percent Efficienc
	7F	None	
	7 ₀	None	
[_]	Mark (X) this box if ye	ou attach a continuation sheet.	

10.09 <u>CBI</u> []	substance in terms of a S residual treatment block source. Do not include r	Identify each emission point source containing the listed tream ID Code as identified in your process block or flow diagram(s), and provide a description of each point aw material and product storage vents, or fugitive emissic leaks). Photocopy this question and complete it separately
	Process type	Encapsulating
	Point Source ID Code	Description of Emission Point Source
	_7F	Work Bench Hooded Ventillation System
		•

Mark (X) this

рох Х

if

_	<u>State</u>	Emissions (kg/day)	Frequency ² (days/yr)	Duration (min/day)	Average Emission Factor ⁴	Emission Rate (kg/min)	Rate Frequency (events/yr)	Emission Rate Duration (min/event
	Υ	("UK")	50	_12_	("U.K.")	("U.K.")	50	12
			~					
								. =
								··· · · · · · · · · · · · · · · · · ·

³Duration of emission at any level of emission

 $^{^4}$ Average Emission Factor — Provide estimated (\pm 25 percent) emission factor (kg of emission per kg of production of listed substance)

CBI			Stack	completing				•
	Point Source ID Code	Stack <u>Height(m)</u>	Inner Diameter (at outlet) (m)	Exhaust Temperature (°C)	Emission Exit Velocity (m/sec)	Building <u>Height(m)</u> ¹	Building Vidth(m)	Vent Type
	Art Permit FR 2235	6.4 TH 9 Abov	.5	Ambient	("u.K")	NA	MA	
	FR 2232	8.5 TH 3 Above		Ambient	("U.K.")	NA	NA	
	¹ Height o	f attached	or adjacent	building				
	² Width of	attached o	or adjacent b	ouilding				
	³ Use the	following o	codes to desi	ignate vent	type:			
	H = Hori; V = Vert:							
							. •	
	•							

10.12	If the listed substance is emitted in particul distribution for each Point Source ID Code ide Photocopy this question and complete it separa	entified in question IO OO
<u>CBI</u>	Point source ID code	
	Size Range (microns)	
	< 1	Mass Fraction (% ± % precision)
	≥ 1 to < 10	
	≥ 10 to < 30	
	≥ 30 to < 50	
	≥ 50 to < 100	
	≥ 100 to < 500	
	≥ 50 0	
		Total = 100%
[<u></u>] M	ark (X) this box if you attach a continuation	sheet.

10.13	Equipment Leaks Complete types listed which are expactording to the specified the component. Do this for residual treatment block for exposed to the listed process, give an overall prexposed to the listed subs	osed to the l weight percest reach procest low diagram(s substance. l ercentage of	listed sulent of the ss type is solution in this is time per	bstance ase listed dentified of includes a batch year tha	nd which a substance in your p e equipmer or interm t the proo	are in se passing process but types wittently tess type	rvice through lock or that are operated is
<u>CBI</u>	for each process type.	tance. FNO((сору пт	s question	r and comp	orece ic	separate.
[_]	Process type						
	Percentage of time per year type	that the li	sted sub	stance is	exposed t	to this p	rocess
		Number	of Compos of Liste	nents in : d Substan	Service by se in Prod	/ Weight less Stre	Percent
	Touris and A. Tro	Less					Greate:
	Equipment Type	than 5%	5-10%	11-25%	26-75%	76-99%	than 99
	Pump seals¹						
	Packed						
	Mechanical						
	Double mechanical ²						
	Compressor seals ¹						
	Flanges						
	Valves (NA)						
	Gas ³						
	Liquid						
	Pressure relief devices (Gas or vapor only)						
	Sample connections						
	Gas						
	Liquid						
	Open-ended lines ⁵					***	
	(e.g., purge, vent)						
	Gas						
	Liquid						
	¹ List the number of pump ar compressors	nd compressor	seals,	rather th	an the nu	mber of p	oumps or
10.13	continued on next page						
<u></u>	fark (X) this box if you at	tach a contin	nuation s	heet.			

10.15	(2011/11/1023)			
	² If double mechanical seals greater than the pump stude will detect failure of the with a "B" and/or an "S",	ffing box pressure a e seal system, the b	nd/or equipped wit	h a concor /Cl .L.
	³ Conditions existing in the	e valve during norma	l operation	
	Report all pressure relief control devices	f devices in service	, including those	equipped with
	⁵ Lines closed during normal operations	l operation that wou	ld be used during	maintenance
10.14 <u>CBI</u>	Pressure Relief Devices with pressure relief devices idented devices in service are contenter "None" under column of	entified in 10.13 to crolled. If a press	indicate which no	escure relief
·	a. Number of Pressure Relief Devices	b. Percent Chemicalin Vessel	c. Control Device	d. Estimated Control Efficiency
			-	
	NA)		
				
				*
	Defens to the table in			
	Refer to the table in quest heading entitled "Number of Substance" (e.g., <5%, 5-10	Components in Serv	d the percent rangice by Weight Per	ge given under the cent of Listed
;	The EPA assigns a control e with rupture discs under no efficiency of 98 percent fo conditions	rmal operating cond	itions. The EPA:	assigns a control
[_] +	Mark (X) this box if you att	ach a continuation	sheet.	

BI						
<u>_</u>]	Process type	• • • • • • • • • • • • • • • • • • • •	• • • • • • • • • • • • •	(NA)		
		Leak Detection Concentration (ppm or mg/m³) Measured at Inches	- Detection	Frequency of Leak Detection		Repair: Complete
	Equipment Type	from Source	<u>Device¹</u>		detection)	initiated
	Pump seals					
	Packed					_
	Mechanical					
	Double mechanical					
	Compressor seals					
	Flanges					
	Valves					
	Gas					
	Liquid					
	Pressure relief devices (gas or vapor only)					
	Sample connections					
	Gas					
	Liquid					
	Open-ended lines					
	Gas					
	Liquid					
	•					
	1 Use the following co POVA = Portable orga FPM = Fixed point mo O = Other (specify)	nic vapor analyze		evice:		

	D)				Vessel	Vessel		Operat ing					
Vessel Roof of Stored (liters Rate Da	Filling Duration (min)	Inner Diameter (m)	Vessel Height (m)	Vessel Volume	Vessel Emission Controls	Design Vent Flow Diameter Rate (cm)	Diameter	Control Efficiency (%)	Basis for Estimate				
		(NA)					·					
					-								
 · ¹lise th	e followi	ng codes to	designate ves	sel type		²Use	the fol		codes to d	 esionat	e floating	roof seals	
F = CIF = NCIF = EFR =	Fixed ro Contact Noncontac External	of internal floa ct internal i floating roo	ating roof floating roof	i.		MS1 MS2 MS2R LM1	= Mech = Shoe = Rim- = Liqu	nanical mounte -mounted uid-moun	shoe, prim d secondar , secondar ted resili shield	ary y y			•
H =	Horizonta Undergrou	al	·	J	•	emu VM1 VM2	= Weat = Vapo = Rim-	hershi rmount	eld ed resilie secondary	nt fille	ed seal, p	orimary	
³ Indica	te weight	percent of t	the listed su	bstance.	Include	the total	volati	le orga	nic conten	t in pai	renthesis		
		ing roofs								•			
5Gas/va	por flow r	ate the emis	sian cantrol	device v	as design	ed to hand	dle (sp	ecify f	low rate ur	nits)			
⁶ Use the	e followin	g codes to d	lesignate bas	is for e	stimate of	control e	efficie	ncy:					
C = Ca	lculations	•											

10.23	Indicate the date and time when the release occurred and when the release ce	eased or
	was stopped. If there were more than six releases, attach a continuation she list all releases.	neet and

Release	Date Started	Time (am/pm)	Date Stopped	Time (am/pm)
1	•			
2				
$\frac{3}{NA}$				···.
	-			· .
5				
6	***			

10.24 Specify the weather conditions at the time of each release.

Release	Wind Speed (km/hr)	Wind Direction	Humidity (%)	Temperature (°C)	Precipitatio (Y/N)
3					
4					
5					
´ 		-			

APPENDIX I: List of Continuation Sheets

Attach continuation	sheets for sections of this form and optional information after this	
page. In column 1,	clearly identify the continuation sheet by listing the question number. In column 2, enter the inclusive page numbers of the continuation	_

	Question Number(1)	Continua Shee Page Nu (2)	t mbers
None			
		-	
		•	
		-	
Mark (X) ti	is box if you attach a continuation	sheet.	

APPENDIX II: Substantiation Form and Instructions to Accompany Claims of Confidentiality Under the Comprehensive Assessment Information Rule (CAIR)

If you assert one or more claims of confidentiality for information submitted on a Comprehensive Assessment Information Rule (CAIR) form, please answer, pursuant to 40 CFR 740.219, all the following questions in the space provided. Type all responses. If you need more space to answer a particular question, please use additional sheets. If you us additional sheets, be sure to include the section, number, and (if applicable) subpart of the question being answered, and write your facility's name and Dun & Bradstreet Number: the lower right-hand corner of each sheet. A completed copy of this form must accompany all submissions containing one or more claims of confidentiality. Failure to do so will result in the waiver of your claim of confidentiality.

EPA has identified six information categories as those which encompass all claims of confidentiality. These are: Submitter identity (h); Substance identity (i); Volume manu factured, imported, or processed (j); Use information (k); Process information (l); and Other information (m). Respondents who assert a CBI claim on the reporting form must mar the letter(s) (h through m) that represent(s) the appropriate category(ies) of confidentiality in the box adjacent to the question, and answer the questions in this form.

Respondents who assert a CBI claim for information submitted under CAIR must also provide EPA with sanitized and unsanitized versions of their submissions. The unsanitize version must be complete and contain all information being claimed as confidential. The sanitized copy must contain only information not claimed as confidential. EPA will place the second copy of the submission in the public file. Failure to submit the second copy the form at the time the respondent submits the reporting form containing confidential information or after receipt of a notice from EPA thereafter will result in a waiver of t respondent's claim of confidentiality.

Please indicate the CAS Registry Number (if known) or chemical name (if the CAS Registry Number is not known) for the substance that is the subject of this form: 584-84-9

If you are reporting on a tradename, please provide the tradename for the substance that the subject of this form:

Stepanfoam G-308-T

Does this form contain CBI? [] Yes

[X] No

If the answer to this question is yes, you must bracket the text claimed as CBI. Any unbracketed information may be placed in the public file.

1	Mark	(X)	this	pox	if	you	attach	a	continuation	sheet.
---	------	-----	------	-----	----	-----	--------	---	--------------	--------